



MILLTOWN GREENLINE PHOTOS: 2010 - 2024

September 2024

PREPARED FOR:



Natural Resource Damage Program

1720 9th Avenue
PO Box 201425
Helena, Montana 59620-1425

PREPARED BY:



Geum Environmental Consulting, Inc.

307 State Street
Hamilton, Montana 59840

Cover Image:

*Floodplain wetlands upstream of the Clark Fork & Blackfoot River confluence. September 2024.
Geum Environmental Consulting, Inc.*



Figure 1. CFR2 greenline photo point locations.



Figure 2. CFR3A greenline photo point locations.



Figure 3. CFR3B greenline photo point locations.

CFR 2: GL-1



2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-2

2010



Note: Channel migration following Spring 2011 flooding made this point inaccessible for repeat monitoring in 2011.

2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-3



2012



2013



2014



2015



2016




2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-3 (Upstream @ side channel)

Note: Upstream side channel view captured beginning in 2015

2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-4

2010



2011



2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-5



2013



2014



2015



2016



2017



2018 (Upstream)



2018 (Downstream)



2019 (Upstream)



2019 (Downstream)



2020 (Upstream)



2020 (Downstream)



2021 (Upstream)



2021 (Downstream)



2022 (Upstream)



2022 (Downstream)



2023 (Upstream)



2023 (Downstream)



2024 (Upstream)



2024 (Downstream)



CFR 2: GL-6



2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 2: GL-7

Note: GL-7 was established in 2011 to document treatments implemented at the confluence of the Clark Fork and Blackfoot Rivers post 2010 monitoring.

2011



2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3A: GL-1



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3A: GL-2



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3A: GL-3



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3A: GL-4



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3A: GL-5



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022




2023



2024



CFR 3A: GL-6



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3B: GL-1



2012



2013



2014



2015



2016



2017



2018



2019





2023



2024



CFR 3B: GL-2

2010



2011



2012



2013



2014



2015



2016



2017



2018



2019



2020



Note: 2020 photo taken ~100 ft upstream from depositional feature – see 2019 photo for 2020 location.

2021



2022



2023



2024



CFR 3B: GL-3



2012



2013 (original location)



Note: In 2013, GL-3 was moved approximately 150 feet to the southwest to capture the existing channel alignment.

2013 (new location)



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3B: GL-4



Note: In 2011, the GL-4 field of view was expanded to capture the effects of spring flooding.

2012



2013



2014



2015



2016



2017



2018



2019 - Upstream



2019 - Downstream



2020 - Upstream



2020 - Downstream



2021 - Upstream



2021 - Downstream



2022 - Upstream



2022 - Downstream



2023 - Upstream



2023 - Downstream



2024 - Upstream



2024 - Downstream



CFR 3B: GL-5

2010



Note: Photo point GL-5 was lost during the 2011 spring flood.

CFR 3B: GL-6 & 6A

2010



Note: Point GL-6 was inaccessible in 2011 and 2012 due to changes in channel alignment following the 2011 spring flood. GL-6a was established on the opposite bank in 2011 to document the post-flood channel alignment. In 2013, the original GL-6 photo point location was accessible again, and greenline photos resumed at the original location.

2011 (GL-6A)



2012 (GL-6A)



2013



2014



Note: In 2014, the GL-6 photo point location was moved upstream approximately 150’ to capture the entrance to the left bank side channel.

2015



2016



2017



2018



Note: Taken from same location as 2017. In 2018, the main channel has migrated approximately 100' east.

2019 - Upstream



2019 - Downstream



2020 - Upstream



2020 - Downstream



2021 - Upstream



2021 - Downstream



2022 - Upstream



2022 - Downstream



2023 - Upstream



2023 - Downstream



2024 - Upstream



2024 - Downstream



CFR 3B: GL-7

2010



2011



2012



Note: Photo point GL-7 was moved approximately 500' upstream in 2012 following changes to the channel and left bank resulting from 2011 flooding.

2013



2014



2015



2016



2017





Note: Channel migration in 2018 has resulted in a backwater feature at GL-7. See alternate photos from main channel below.



2019 (Upstream)



2019 (Downstream)



2019 (Mainstem upstream)



2019 (Mainstem downstream)



2020 (Upstream)



2020 (Downstream)



2021 (Upstream)



2021 (Downstream)



2022 (Upstream)



2022 (Downstream)



2023 (Upstream)



2023 (Downstream)



2024 (Upstream)



2024 (Downstream)



CFR 3B: GL-8



2013



2014



2015



2016



2017



2018



Note: Willow growth and high water interfered with ability to capture downstream bankline.

2019



2020



2021



2022



2023



2024



CFR 3B: GL-9

2010



2011



2012



2013



2014



2015



2016



2017



2018



2019



2020



2021



2022



2023



2024



CFR 3B: GL-10



2012



2013



2014



2015



2016



2017



2018



2019



2020



Note: Photopoint location moved inland (west) ~100 ft due to bank erosion.

2021 on

Note: Photopoint location lost to ongoing bank erosion. See CFR3b GL-11 for view of upstream bank where photopoint was originally located.

CFR 3B: GL-11



2012



2013



2014



2015



2016



2017



2018



2019





Note: Photopoint location moved to capture extents of bank erosion. Bank upstream of photopoint (including GL-10 photopoint location) is eroded to mature tree/shrubs.

2022



2023



2024

